

**BULLETIN #2**  
**EPWU Cross-Connection Control Program**

Date: August 18, 2006

To: Certified Backflow Prevention Assembly Test Technicians

From: El Paso Water Utilities Cross-Connection Control Program Manager

El Paso Water Utilities is having problems with water service being turned on new meter installations with backflow preventers (BFPs) and never receiving test reports for same.

In order to prevent this situation, effective immediately all BFP test technicians will be required to carry blank test forms with them when testing BFPs and to provide the EPWU inspector witnessing the test with an original of the test report immediately after a passing test is completed. You will be required to make two identical originals – one for your records and one for the inspector. Test techs should not rely on the inspector to furnish these forms. The inspector will be instructed to turn off the water after a test is completed unless he receives an original test report.

Your cooperation is appreciated. Please call the Cross-Connection Control Program Manager at 594-5777 if you have any questions.